

NARRATIVE REPORT

**DNR/Office of Conservation
Operations Division**

Serial Number	Date 06/29/12	Operator ()
Lease Name		Address
Location (Sec, Twp, Rng / Parish) Assumption		
Field Napoleonville	()	Phone () -
		Contact

REMARKS

Inspections in Napoleonville

C.E.S. Barras and Theriot traveled to Bayou Corne boat landing with Whaler I to meet with C.E.S Oubre

and DEQ agent Danny Burgard to perform inspections in the Napoleonville, Bayou Corne and Grand Bayou

Fields concerning the bubbles associated with pipelines in the area -- The Following wells sites on water were

inspected and no bubbles were found: Ser # 14169, # 45869, # 44441. Two land locations: Ser # 30847

and # 202913 were inspected and no bubbles were found --

Bubbles were detected at 5 water sites:

Site 1 -- Was a Crosstex pipeline crossing Bayou Corne @ GPS Reading: North - 30dg 00' 24.8" West - 91dg 08' 46.4" --

Site 2 -- Was Acadian Gas Pipeline crossing Bayou Corne @ GPS Reading: North - 30dg 00' 24.2" West - 91dg 08' 44.7"

Site 3 -- Was a site marked by a 3/4" PVC pipe @ GPS Reading: North - 30dg 00' 10.6" West - 91dg 08' 11.3"

Site 4 -- Was a site marked by a 3/4" PVC pipe @ GPS Reading: North - 30dg 00' 30.1" West - 91dg 08' 05.9"

Site 5 -- Was a site marked by a 3/4" PVC pipe @ GPS Reading: North - 30dg 00' 12.8" West - 91dg 08' 09.7"

At each site DEQ Agent, Danny Burgard, use an I/R camera to scan the bubbles sites for Hydrocarbons,

no measurable readings were detected --

The remaining 9 well sites selected for inspection will require an air boat and a 4 wheeler to access these

well site: Ser # 31279, 47499, 147615, 31536, 13073, 61481, 30948, 55963, and 30973 --

Chee Wee

Personnel on inspections:

Chee Wee -- C.E.S

Bret Barras -- C.E.S

Michael Theriot -- C.E.S

Danny Burgard -- D.E.Q -- Ph. # 225-252-0407

